

## GOVERNMENT OF TRIPURA PUBLIC WORKS DEPARTMENT (R&B) OFFICE OF THE EXECUTIVE ENGINEER JIRANIA DIVISION, JIRANIA, TRIPURA (W)

## **BUILDING SAFETY CERTIFICATE**

Name of Institution

BETHANY SCHOOL, EAST CHAMPAMURA,

KHAYERPUR, WEST TRIPURA

Type of Building

RCC FRAMED STRUCTURE

DOUBLE STORIED BUILDING

Certified that, the Building of Bethany School located at East Champamura, Khayerpur, West Tripura appears to be a SAFE STRUCTURE as of present condition.

Usually these sorts of Structure have a general Life Span of 50(Fifty) Years if periodical maintenance & renovation works are carried out.

However, it appears that, the above Building Structure is a Safe Structure for a further period of 10 (TEN) years.

This Certificate is issued based on VISUAL OBSERVATION and taking in to account the PLAN & STRUCTURAL DRAWING of the Building as well as present physical appearance.

I wish bright & prosperous future of the Institution.

(Er. S. N. Sarkar) in e<sup>el</sup> Executive Engineer (R Jirania Division RivD(R&B) Jirania, **Rest** Fripura

NO. 01/CERT/EE/PWD(R&B)/JRN/2021-22

Manager

Manager

BETHANY SCHOOL

East Champamura,

Old Agartala, Khayerpur,

Tripura Wost Pin-799008

Principal
BETHAN SCHOOL
East Champamura,
Old Agartala, Khayerpur,
Tripura West, Pin-799008